

FEB 09 1982

DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

April 20, 1977

CI-726-101

*DPM 5477*  
*Compound, Molding Phenolic*

Fiberite West Coast Corporation  
645 North Cypress Avenue  
Orange, California 92666

Gentlemen:

This facility must, on occasion, reship your product, Phenolic Molding Compound, #FM-3510.

In order to insure our compliance with the Hazardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your product is a regulated or restricted article for shipment by surface or air modes of transport.

Should the product be regulated, please indicate:

1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
2. DOT Hazard Classification per Section 172.101, 49 CFR.
3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet if available.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

*M. J. Veneroso*  
M. J. Veneroso, Dept. CI-726 (52-11)  
Materials Handling & Packaging Engineering  
Douglas Aircraft Company

WTJ:rc

MCDONNELL DOUGLAS  
CORPORATION

BOE-C6-0202887